



# Intel<sup>®</sup> Ethernet Controller Products

## 31.0 Release Notes

---

*January 2026*

## Revision History

Revision	Date	Comments
3.6	January 2026	Release Notes 31.0 (Version 1): <ul style="list-style-type: none"> <li>• 2025R3.1 Updates</li> <li>• E610: Restored support for Windows Server 2019/Windows 10</li> <li>• Added support for Azure Local 2511 OS and FreeBSD 15.0 OS</li> </ul>
3.5	December 2025	Release Notes 30.6 (Version 1): <ul style="list-style-type: none"> <li>• 2025R3 Updates</li> <li>• Introducing new support for:               <ul style="list-style-type: none"> <li>– Intel® Ethernet Network Adapter E810-XXVDA2 Support</li> <li>– Intel® Ethernet Network Adapter OCP3.0 E810-XXVDA2</li> <li>– Intel® Ethernet Network Adapter E830-XXVDA4F</li> </ul> </li> <li>• Added new OS support for RHEL 10.1 and RHEL 9.7</li> </ul>
3.4	December 2025	Release Notes 30.5.1 (Version 2): <ul style="list-style-type: none"> <li>• Split the E830 series into two rows for the NVM Versions Supported - <a href="#">Table 5</a></li> </ul>
3.3	November 2025	Release Notes 30.5.1 (Version 1): <ul style="list-style-type: none"> <li>• Added new support SUSE SLE 16, Windows 11 25H2 for i40ea &amp; i40eb</li> </ul>
3.2	October 2025	Release Notes 30.5 (Version 1): <ul style="list-style-type: none"> <li>• Refresh and custom bugfixes for Dell</li> <li>• Added new support Windows 11 25H2</li> <li>• Tools and drivers support for a new Intel E610 controller chip which can operate in -40 to 85°C</li> <li>• E825: NC-SI 1.2 support for E825 (Phase 1+2+3)</li> <li>• E825: Support NCSI-over-RMII Control-Only Mode (no Passthrough)</li> <li>• E825: NC-SI 1.2 Get Pass-through Mode</li> <li>• Removed Windows 11 21H2 Support - EOL</li> <li>• Removed Windows 11 22H2 Support - EOL</li> </ul>
3.1	September 2025	Release Notes 30.4.2 (Version 1): <ul style="list-style-type: none"> <li>• Refresh and bugfixes for ESXi 8.0 and 9.0 drivers for 10G and 40G</li> </ul>
3.0	September 2025	Release Notes 30.4.1 (Version 1): <ul style="list-style-type: none"> <li>• Introducing new OS Support ESXi 9.0</li> </ul>
2.9	August 2025	Release Notes 30.4 (Version 1): <ul style="list-style-type: none"> <li>• 2025R2 updates</li> </ul> Release Notes 30.4 (Version 2): <ul style="list-style-type: none"> <li>• Removed all ESXi 9.0 information</li> <li>• Removed FW support for X710 - Modern standby for workstation</li> <li>• Updated the NVM table for E830, E820, E610 series and added E825 series</li> <li>• Added E825 fixes in Fixed Issue section</li> <li>• Added Thermal sensor information and support in Firmware support</li> </ul>
2.8	July 2025	Release Notes 30.3: <ul style="list-style-type: none"> <li>• Introducing new support SUSE Linux Enterprise Server 15 SP7</li> </ul>
2.7	July 2025	<ul style="list-style-type: none"> <li>• (Internal Release Only)</li> </ul>

Revision	Date	Comments
2.6	July 2025	<p>Release Notes 30.2:</p> <ul style="list-style-type: none"> <li>• Introducing support for new NICs (Only Linux are supported): <ul style="list-style-type: none"> <li>– Intel(R) Ethernet Network Adapter E830-XXV-8F for OCP 3.0</li> <li>– Intel(R) Ethernet Network Adapter E830-C-Q2</li> <li>– Intel(R) Ethernet Network Adapter E830-C-Q2 for OCP 3.0</li> <li>– Intel(R) Ethernet Controller E830-CC for QSFP</li> <li>– Intel(R) Ethernet Controller E830-CC for SFP</li> <li>– Intel(R) Ethernet Connection E825-C 10GbE</li> <li>– Intel(R) Ethernet Connection E825-C for QSFP</li> <li>– Intel(R) Ethernet Connection E825-C for SFP</li> <li>– Intel(R) Ethernet Connection E825-C for backplane</li> <li>– Intel(R) Ethernet Network Adapter E830-XXV-2 for OCP 3.0</li> <li>– Intel(R) Ethernet Network Adapter E830-XXV-2</li> <li>– Intel(R) Ethernet Controller E830-XXV for SFP</li> </ul> </li> </ul>
2.5	June 2025	– (Internal Release Only)
2.4	June 2025	<p>Release Notes 30.1.1:</p> <ul style="list-style-type: none"> <li>• Introducing New OS support Red Hat Enterprise Linux 9.6 and 10.0</li> </ul>
2.3	June 2025	<p>Release Notes 30.1.0.1:</p> <ul style="list-style-type: none"> <li>• Linux drivers point release with critical fix</li> </ul>
2.2	April 2025	<p>Release Notes 30.1:</p> <ul style="list-style-type: none"> <li>• 2025R1 Updates</li> </ul>
2.1	February 2025	<p>Release Notes 30.0.1:</p> <ul style="list-style-type: none"> <li>• Introducing support for new NICs (part of Intel® Ethernet 10 Gigabit Adapters): <ul style="list-style-type: none"> <li>– Intel® Ethernet Network Adapter E610-XT2</li> <li>– Intel® Ethernet Network Adapter E610-XT4</li> <li>– Intel® Ethernet Network Adapter E610-IT4</li> </ul> </li> </ul>
2.0	February 2025	<p>Release Notes 30.0:</p> <ul style="list-style-type: none"> <li>• Introducing support for new NICs (part of Intel® Ethernet 10 Gigabit Adapters): <ul style="list-style-type: none"> <li>– Intel® Ethernet Controller E610 for 10GBASE-T</li> <li>– Intel® Ethernet Network Adapter E610-IT4 for OCP 3.0</li> </ul> </li> </ul>
1.9	December 2024	<p>Release Notes 29.5:</p> <ul style="list-style-type: none"> <li>• Introducing New OS support: FreeBSD 13.4</li> <li>• 2024R5 Updates</li> </ul>
1.8	November 2024	<p>Release Notes 29.4.1:</p> <ul style="list-style-type: none"> <li>• Introducing New OS support: Red Hat Enterprise Linux 9.5</li> </ul>
1.7	October 2024	<p>Release Notes 29.4:</p> <ul style="list-style-type: none"> <li>• Introducing New OS support: Windows Server 2025 and Windows 11 24H2 OSes</li> </ul>
1.6	August 2024	<p>Release Notes 29.3.1:</p> <ul style="list-style-type: none"> <li>• Introducing New OS support: Ubuntu 24.04 LTS</li> </ul>
1.5	August 2024	<p>Release Notes 29.3:</p> <ul style="list-style-type: none"> <li>• Generic update for FVL, CVL and CPK NIC OEM and FreeBSD 14.1</li> </ul>
1.4	July 2024	<p>Release 29.2.1:</p> <ul style="list-style-type: none"> <li>• Introducing New OS support: SLES 15 <b>SP6</b></li> </ul>
1.3	July 2024	<p>Release 29.2:</p> <ul style="list-style-type: none"> <li>• Introducing New OS support: VMware ESXi <b>8.0u3</b></li> </ul>



Revision	Date	Comments
1.2	June 2024	Release 29.1.2: <ul style="list-style-type: none"><li data-bbox="581 344 1396 390">• Introducing New OS Support: Red Hat Enterprise Linux <b>9.4</b> and Red Hat Enterprise Linux <b>8.10</b></li></ul>
1.0	May 2024	Release Notes 29.1: <ul style="list-style-type: none"><li data-bbox="581 438 922 464">• Dot release, ESXi drivers update.</li><li data-bbox="581 470 1153 495">• Full OEM Gen container release for E810, E700 and E820.</li></ul>

## Contents

---

<b>1.0 Overview</b>	<b>7</b>
1.1 New Features	7
1.1.1 Hardware Support	7
1.1.2 Software Features	7
1.1.3 Firmware Features	7
1.2 Removed Features	7
1.3 Operating Systems Supported	8
1.3.1 Linux	8
1.4 Windows Server	8
1.4.1 Windows Client	10
1.4.2 FreeBSD	12
1.4.3 ESXi Drivers	12
1.5 NVM Versions Supported	13
1.6 DDP Versions Supported	14
<b>2.0 Fixed Issues</b>	<b>15</b>
2.1 Intel® Ethernet 800 Series Network Adapters	15
2.1.1 Intel® Ethernet 810 Series	15
2.1.2 Intel® Ethernet 820 Series	15
2.1.3 Intel® Ethernet 825 Series	15
2.1.4 Intel® Ethernet 830 Series	16
2.2 Intel® Ethernet 700 Series Network Adapters	16
2.2.1 General	16
2.2.2 Firmware/NVM/NVM Update	16
2.2.3 Windows Driver	16
2.2.4 ESX Driver	16
2.2.5 Pre - boot	16
2.3 Intel® Ethernet I211/I210 Series Network Adapters	16
2.3.1 General	16
2.4 Intel® Ethernet 610 Series Network Adapters	16
2.4.1 General	16
2.4.2 Firmware/NVM/NVM Update	17
2.4.3 Windows Driver	17
2.4.4 Linux Driver	17
2.4.5 VMware Driver	17
2.4.6 ESX Driver	17
2.5 Intel® Ethernet I350 Series Network Adapters	17
2.5.1 Windows Driver	17
2.6 Intel® Ethernet 500 Series Network Adapters	17
2.6.1 General	17
<b>3.0 Known Issues</b>	<b>18</b>
3.1 Intel® Ethernet 800 Series Network Adapters	18
3.1.1 Intel® Ethernet 810 Series	18
3.1.2 Intel® Ethernet 820 Series	19
3.1.3 Intel® Ethernet 825 Series	20
3.1.4 Intel® Ethernet 830 Series	20
3.2 Intel® Ethernet 700 Series Network Adapters	21
3.2.1 General	21
3.2.2 Intel® Ethernet Controller V710-AT2/X710-AT2/TM4	21
3.2.3 Linux Driver	22
3.2.4 Pre-Boot	22
3.2.5 ESX Driver	22

3.2.6	Firmware/NVM/NVM Update .....	22
3.2.7	Windows Driver .....	22
3.2.8	ESX Driver .....	22
3.3	Intel® Ethernet 600 Series Network Adapters .....	23
3.3.1	General .....	23
3.3.2	Linux Driver .....	23
3.3.3	Windows Driver .....	23
3.3.4	VMware Driver .....	23
3.3.5	Firmware/NVM/NVM Update .....	23
3.3.6	ESX Driver .....	23
3.4	Intel® Ethernet 500 Series Network Adapters .....	23
3.5	Intel® Ethernet I350 Series Network Adapters .....	24
3.6	Legacy Devices .....	24
<b>4.0</b>	<b>NVM Upgrade/Downgrade 800 Series/700 Series/600 series and X550 .....</b>	<b>25</b>
<b>5.0</b>	<b>Languages Supported .....</b>	<b>25</b>
<b>6.0</b>	<b>Related Documents .....</b>	<b>25</b>
6.1	Feature Support Matrix .....	25
6.2	Specification Updates .....	26
6.3	Software Download Package .....	26
6.4	GitHub Ethernet Drivers and Utilities .....	26
6.5	Intel Product Security Center Advisories .....	26

## 1.0 Overview

This document provides an overview of the changes introduced in the latest Intel® Ethernet Controller/ Adapter family of products. References to more detailed information are provided where necessary. The information contained in this document is intended as supplemental information only; it should be used in conjunction with the documentation provided for each component.

These release notes list the features supported in this software release, known issues, and issues that were resolved during release development.

### 1.1 New Features

#### 1.1.1 Hardware Support

Release	New Hardware Support
31.0	<ul style="list-style-type: none"><li>None for this release.</li></ul>

#### 1.1.2 Software Features

Release	New Software Support
31.0	<ul style="list-style-type: none"><li>E610: Restored support for Windows Server 2019/Windows 10</li><li>Added new support - FreeBSD 15.0 and Azure Local 2511</li></ul>

#### 1.1.3 Firmware Features

Release	New Firmware Support
31.0	<ul style="list-style-type: none"><li>None for this release.</li></ul>

### 1.2 Removed Features

Release	Hardware/Feature Support
31.0	<ul style="list-style-type: none"><li>None for this release.</li></ul>

## 1.3 Operating Systems Supported

### 1.3.1 Linux

Operating Systems supported:

- Linux Kernel 6.x and 5.x
- Linux Real Time Patch 6.x and 5.x
- Kylin Linux Advance Server V10 (only for Intel Ethernet E810 Series)
- Red Hat \*Enterprise Linux\* (RHEL) 10.1
- Red Hat Enterprise Linux (RHEL) 10.0
- Red Hat Enterprise Linux (RHEL) 9.7
- Red Hat Enterprise Linux (RHEL) 9.6
- SUSE Linux Enterprise Server 16
- SUSE Linux Enterprise Server 15 SP7
- SUSE Linux Enterprise Server 15 SP6
- Canonical Ubuntu 24.04 LTS
- Canonical \*Ubuntu\* 22.04 LTS
- Debian\* 11 (not available for Intel Ethernet E610 Series)
- openEuler (not available for Intel Ethernet E610 Series)

**Table 1. Supported Operating Systems: Linux**

Product	PF Driver	VF Driver	RDMA Driver
<b>Intel® Ethernet 810/820/830 Series</b>	2.4.5	4.13.20	2.5.21
<b>Intel® Ethernet 700 Series</b>	2.28.16	4.13.20	2.5.21
<b>Intel® Ethernet 10 Gigabit Adapters</b>	6.3.4	5.2.2	Not Supported
<b>Intel® Ethernet Gigabit Adapters</b>	5.19.10	Not Supported	Not Supported

## 1.4 Windows Server

Operating Systems supported:

- Microsoft Windows Server 2025
- Microsoft Windows Server 2022
- Microsoft Windows Server 2019, Version 1903
- Microsoft Windows Server 2016 (Not available for Intel Ethernet E610 Series)
- Microsoft Azure Stack HCI

**Table 2. Supported Operating Systems: Windows Server**

Driver	Windows Server 2025	Windows Server 2022	Windows Server 2019	Windows Server 2016
<b>Intel® Ethernet 800 Series</b>				
<b>icea</b>	1.20.43.0	1.20.39.0	1.20.45.0	1.14.104.0
<b>iceb</b>	1.2.78.0	1.2.77.0	1.2.78.0	Not Supported
<b>scea</b>	1.18.79.0	1.18.76.0	1.18.77.0	Not Supported
<b>sceb</b>	1.17.47.0	1.17.48.0	Not supported	Not Supported
<b>Intel® Ethernet 700 Series</b>				
<b>i40ea</b>	1.24.44.0	1.24.41.0	1.24.42.0	1.18.369.0
<b>i40eb</b>	1.24.41.0	1.24.41.0	1.24.41.0	1.18.369.0
<b>Intel® Ethernet Adaptive Virtual Function</b>				
<b>iavf</b>	1.18.158.0	1.18.161.0	1.18.162.0	1.14.203.0
<b>Intel® Ethernet 600 Series / Intel® Ethernet 10 Gigabit Adapters and Connections</b>				
<b>ixs</b>	4.2.7.0	4.1.254.0	4.1.254.0	4.1.254.0
<b>sxa</b>	4.2.9.0	4.1.254.0	4.1.254.0	4.1.254.0
<b>sxb</b>	Not Supported	4.1.254.0	4.1.254.0	4.1.254.0
<b>ixt</b>	Not Supported	Not Supported	4.1.228.0	4.1.229.0
<b>ixn</b>	Not Supported	Not Supported	4.1.254.0	4.1.254.0
<b>ixw</b>	1.6.25.0	1.6.25.0	1.6.25.0	Not Supported
<b>vxs</b>	2.3.7.0	2.3.7.0	2.1.252.0	2.1.232.0
<b>vxn</b>	Not Supported	Not Supported	2.1.252.0	2.1.252.0
<b>Intel® Ethernet 2.5 Gigabit Adapters and Connections</b>				
<b>e2f</b>	2.1.5.7	1.1.4.45	1.1.4.45	Not Supported
<b>Intel® Ethernet Gigabit Adapters and Connections</b>				
<b>e1r</b>	14.1.24.0	14.0.13.0	14.0.7.0	14.0.6.0

### 1.4.1 Windows Client

Operating Systems Supported:

- Microsoft Windows 11 25H2
- Microsoft Windows 11 24H2
- Microsoft Windows 11 23H2
- Microsoft Windows 10 21H2
- Microsoft Windows 10 RS5, Version 1809

**Table 3. Supported Operating Systems: Windows Client**

Driver	Windows 11	Windows 10 21H2 / Windows 10 RS5
<b>Intel® Ethernet 800 Series</b>		
<b>icea</b>	1.20.46.0	1.20.45.0
<b>Intel® Ethernet 700 Series <sup>1</sup></b>		
<b>i40ea</b>	1.24.41.0	1.24.42.0
<b>i40eb</b>	1.24.45.0	1.24.41.0
<b>Intel® Ethernet Adaptive Virtual Function</b>		
<b>iavf</b>	1.18.161.0	1.18.162.0
<b>Intel® Ethernet 10 Gigabit Adapters and Connections</b>		
<b>ixs</b>	4.1.267.0	4.1.254.0
<b>ixt</b>	Not Supported	4.1.228.0
<b>ixn</b>	Not Supported	4.1.254.0
<b>ixw</b>	1.6.25.0	1.6.25.0
<b>vxS</b>	Not Supported	2.1.252.0
<b>vxn</b>	Not Supported	2.1.252.0
<b>Intel® Ethernet 2.5 Gigabit Adapters and Connections</b>		
<b>e2fn</b>	2.1.5.7	1.1.4.45
<b>Intel® Ethernet Gigabit Adapters and Connections</b>		
<b>e1r</b>	14.1.24.0	14.0.7.0
<b>e1d</b>	12.19.2.64	21H2: 12.19.2.65 RS5: 12.18.9.10
<b>e1dn</b>	20.0.3.24	Not Supported

**Table 3. Supported Operating Systems: Windows Client [continued]**

Driver	Windows 11	Windows 10 21H2 / Windows 10 RS5
<b>e1c</b>	Not Supported	Not Supported
<b>v1q</b>	Not Supported	1.4.7.3

1. For i40ea and i40eb:
  - Supported, validated and certified on Windows 11 24H2
  - Only supported on Windows 11 25H2

## 1.4.2 FreeBSD

Operating Systems supported:

- FreeBSD 15.0
- FreeBSD 14.3

**Table 4. Supported Operating Systems: FreeBSD**

Driver	PF Driver	VF Driver	RDMA Driver
Intel® Ethernet 810/820 Series	2.0.16	3.1.6	1.3.55
Intel® Ethernet 700 Series	1.14.2	3.1.6	1.3.55
Intel® Ethernet 10 Gigabit Adapters	3.4.37	1.6.12	Not Supported
Intel® Ethernet Gigabit Adapters	2.5.31	Not Supported	Not Supported

## 1.4.3 ESXi Drivers

**Note:** Intel® ESXi drivers are available from VMware.

- VMWare ESXi 9.0
- VMWare ESXi 8.0

Refer to VMWare's download site for the latest ESXi drivers for Intel® Ethernet® devices.

## 1.5 NVM Versions Supported

The following table shows the NVM versions supported in this release.

**Table 5. Current NVM**

Product	NVM Version
<b>810 Series</b>	
<b>E810</b>	4.91
<b>820 Series</b>	
<b>E822</b>	3.44
<b>E823-C</b>	3.44
<b>E823-L</b>	3.44
<b>825 Series</b>	
<b>E825</b>	4.03
<b>830 Series</b>	
<b>E830</b>	1.20
<b>700 Series</b>	
<b>X710</b>	9.56
<b>X722</b>	6.50
<b>600 Series</b>	
<b>E610</b>	1.41
<b>500 Series</b>	
<b>X550</b>	3.70
<b>X552NS</b>	2.10
<b>X552DE</b>	2.10
<b>X553</b>	2.10
<b>200 Series</b>	
<b>I210</b>	2.00
<b>I225</b>	1.00

## **1.6 DDP Versions Supported**

The following table shows the versions supported in this release.

**Table 6. Current DDP**

<b>Package</b>	<b>DDP Version</b>
OS Package	1.3.53.0
Comms Package	1.3.61.0
Wireless Edge Package	1.3.25.0

## **2.0 Fixed Issues**

### **2.1 Intel® Ethernet 800 Series Network Adapters**

#### **2.1.1 Intel® Ethernet 810 Series**

##### **2.1.1.1 General**

- None in this release.

##### **2.1.1.2 Firmware/NVM/NVM Update**

- None in this release.

##### **2.1.1.3 Linux**

- None in this release.

##### **2.1.1.4 Windows Driver**

- None in this release.

##### **2.1.1.5 Windows Server**

- None for this release.

##### **2.1.1.6 ESX Driver**

- None for this release.

##### **2.1.1.7 Pre-Boot**

- None for this release.

#### **2.1.2 Intel® Ethernet 820 Series**

##### **2.1.2.1 General**

- None for this release.

##### **2.1.2.2 Firmware/NVM/NVM Update**

- None for this release.

##### **2.1.2.3 Linux Driver**

- None for this release.

#### **2.1.3 Intel® Ethernet 825 Series**

- None for this release.

## **2.1.4 Intel® Ethernet 830 Series**

### **2.1.4.1 General**

- None for this release.

### **2.1.4.2 Linux Driver**

- None for this release.

### **2.1.4.3 Firmware/NVM/NVM Update**

- Add feature support for RDE properties for PortMetrics.Transceivers since version 1.2.

### **2.1.4.4 FreeBSD Driver**

- None in this release.

## **2.2 Intel® Ethernet 700 Series Network Adapters**

### **2.2.1 General**

- None for this release.

### **2.2.2 Firmware/NVM/NVM Update**

- None for this release.

### **2.2.3 Windows Driver**

- None for this release.

### **2.2.4 ESX Driver**

- None for this release.

### **2.2.5 Pre - boot**

- None for this release.

## **2.3 Intel® Ethernet I211/I210 Series Network Adapters**

### **2.3.1 General**

- None for this release.

## **2.4 Intel® Ethernet 610 Series Network Adapters**

### **2.4.1 General**

- None for this release.

## **2.4.2 Firmware/NVM/NVM Update**

- MAC Address set using OS IP tools is not reflected in RDE NetworkDeviceFunction and Port schemas.
- The response for Activate Firmware command does not need to wait for the firmware to complete the internal data dump. The response is just sent before the internal data dump, which works as part of the firmware activation process and followed by calling the Firmware Reset (EMPR).
- E610 may very rarely enter Recovery mode when undergoing excessive AC power cycles.

## **2.4.3 Windows Driver**

- None for this release.

## **2.4.4 Linux Driver**

- None in this release.

## **2.4.5 VMware Driver**

- None in this release.

## **2.4.6 ESX Driver**

- None in this release.

## **2.5 Intel® Ethernet I350 Series Network Adapters**

### **2.5.1 Windows Driver**

- None in this release.

## **2.6 Intel® Ethernet 500 Series Network Adapters**

### **2.6.1 General**

- None in this release.

## 3.0 Known Issues

### 3.1 Intel® Ethernet 800 Series Network Adapters

#### 3.1.1 Intel® Ethernet 810 Series

##### 3.1.1.1 General

- Windows Server 21H1 OS is unable to save memory dump (crash dump) on disk. It is considered to be an OS defect.
- DPDK traffic is stopped after FLR reset. This issue has been documented in the `rte_eth_dev_reset` API.

**Workaround:** `testpmd` can be used to recover a VF after a reset.

- When a VF reset happens, `testpmd` will print out "port reset" event to the console.
- Use the "port reset" command to call `rte_eth_dev_reset`, and everything will go back to normal

##### 3.1.1.2 Firmware/NVM/NVM Update

- None in this release.

##### 3.1.1.3 Linux

- tc filters containing GTP fields failed to be programmed into hardware in switchdev mode
- Configuration of a link down on PF0 in LAG mode resulted in a rping test failure.
- IRDMA SLES RPM installation with `rpm -ivh` may see a conflict with a directory due to multi-kernel installed.

**Workaround:** Use `--force` option to force install the rpm.

- The system crash is observed when user is changing ring size (`ethtool -G`) when Jumbo frames are enabled (MTU 9000) with traffic present.
- DPDK traffic is stopped after FLR reset. This issue has been documented in the `rte_eth_dev_reset` API.

**Workaround:** `testpmd` can be used to recover a VF after a reset.

- When a VF reset happens, `testpmd` will print out "port reset" event to the console.
- Use the "port reset" command to call `rte_eth_dev_reset`, and everything will go back to normal.

- On a Linux host, iavf interfaces in FreeBSD-13.0 guests may experience poor receive performance during stress.

**Workaround:** The workaround for this behavior is to do the power cycle of the setup to see the assigned DCB-MAP is reflecting.

- When user sets more than 8 VLANs for trusted VF, and then moves VF as untrusted, the VLAN configuration will be lost.

**Workaround:** To avoid losing VLAN configuration, user shall first reduce VLANs configuration allowed for untrusted VF (not more than 8 VLANs per VF), and then switch the VF to untrusted mode.

#### 3.1.1.4 FreeBSD Driver

- A PE Critical Error may be observed during traffic in RoCEv2 mode and, using a large number of QPs (>64). In such circumstances the card may become in-operational, and a reboot is required to restore RDMA capability.
- FreeBSD-13.0 guests may experience a poor receive performance on iavf virtual interfaces during stress.

#### 3.1.1.5 RDMA Driver

- None for this release.

#### 3.1.1.6 VMware Driver

- None for this release.

#### 3.1.1.7 Windows Driver

- None for this release.

#### 3.1.1.8 ESX Driver

- Running Unreliable Datagram (UD) RDMA mixed traffic with more than 2 QPs may lead to a receiver side UD application hang.  
**Workaround:** Restart the RDMA UD application. This is not expected to impact storage (NVMeoF, iSER, VSAN) applications since they do not rely on UD communication.
- <VMWARE> When instantiating the maximum number of VFs in NSX-T, adding a Transport Node afterwards might fail due to timeout.

### 3.1.2 Intel® Ethernet 820 Series

#### 3.1.2.1 General

- None for this release.

#### 3.1.2.2 Firmware/NVM/NVM Update

- After advertising the link to 1G in the MRVL system, the link down and up happened 2 times in SUT and a single time in TG.
- Using the EPCT tool to change the port configuration requires 2 reboots to complete the programming process. Blank mode or PTP initialization failures may be observed after a single reboot and will be resolved after performing a second reboot.
- When loading the ICE driver with cages populated, the system displays the error message "Module is not present."
- Module FINISAR CORP.FTRJ8519P1BNL is unable to regain link after issuing a link reset. Recovery requires removing the module from both E825 and switch to reacquire link.
- ethtool gives an invalid argument error when using ethtool -m <interface>.
- When 100mb option is selected in Windows Device Manager, a link cannot be established.
- Lane Reversal is broken preventing proper functionality of 2x1x50g port option on quad 1. CPI opcode 0x67 PortLaneOrder does not support setting lane 1 as the autoneg lane and returns error code 1 (Configuration Error).

### 3.1.2.3 Linux Driver

- None for this release.

### 3.1.2.4 FreeBSD Driver

- None for this release.

### 3.1.2.5 Windows Driver

- None for this release.

### 3.1.2.6 ESX Driver

- Multiple PF resets cause VMXnet3 adapter VFs in ENS mode to fail sporadically, resulting in no traffic.

## 3.1.3 Intel® Ethernet 825 Series

- Inconsistencies in LED behavior during system shutdown for E825-C under S5 state when using PV LEK with "NO MNG" configuration.
- The dmesg log shows "link settings prevent physical link to set to OFF" when unplugging multiple cables at once. This issue seems to be limited to SFP and is under investigation.
- On Azure Stack HCI 23H2, Event Log reports Error 289 during execution of hyperv.basic.large\_send\_offload\_vf. This behavior is unexpected and is currently under investigation.
- It is observed that Traffic Classes for Tx queues are set to ZERO, when the DCB is configured and traffic with VLANs are sent.
- No traffic (ICMP, tcp, udp) after VF reset with NSX-T and DS configuration.
- After enabling PCI passthrough on different adapter there is no traffic.
- It is observed that forcing link speed to 1GbE for e823 with fibre optics cable causing netlink errors.
- NC-SI Health Status 0x508 / 0x507 is not generated, when Global Health Status is enabled.
- When CISCO-OPLINK TRMTFEAS1CCISE1G modules are inserted without fiber, the system incorrectly shows the link as active. LEDs turn on and ethtool reports link up, even though no physical connection exists.

## 3.1.4 Intel® Ethernet 830 Series

### 3.1.4.1 General

- Large number of UDP threads can cause traffic to go to very low throughput.

### 3.1.4.2 Firmware/NVM/NVM Update

- Sysfs ' echo 1 > /sys/bus/pci/devices/<PCI BUS address>/remove' command might cause the order the devices probed to change. If this is the case, the subsequent ice driver probe attempts might end up in kernel WARNING around PTP initialization, if removed PCI device is PF0. PF0 is usually a source timer owner for the devices handled by ice driver (like E825C or E830 devices) and it is a control PF for other PFs. So, non-PF0 devices require PF0 to be initialized first for a successful initialization.

**Workaround:** If the current device probe order is disturbed, the user needs to remove all other PFs as well (PF0 as the first one) and rescan PCI bus then.

- An unrecoverable netlist error is observed during driver attach on FreeBSD 14.0 when using the ice-1.41.8 driver with certain NVM images. The error appears in dmesg after loading the driver, even though functionality does not seem impacted.

### 3.1.4.3 Linux Driver

- There is issue with changing msix\_eth value via devlink param interface - some settings of it on E830 cards cause bandwidth degradation.
- VF fails to create the expected Flow Director rules, halting due to hardware resource limitations.
- Flow Director rules do not correctly steer traffic on Geneve tunnels, causing packets to hit random queues instead of the specified queue.
- Stack trace occurs when CRC strip and VLAN strip are enabled together on RHEL 8.9 with ice PF driver 2.0.0\_rc21.
- Performing devlink dev reload on PF after changing VF MSI-X allocation triggers errors in dmesg and impacts VF creation.
- Running the devlink reload command on CVL/CNV hardware with driver versions 1.16.3 or 2.0.11 on Fedora 6.11.9 causes a WARN\_ON call trace and the error "unable to move VSI idx 1 into aggregator 1 node." The reload operation fails instead of completing successfully.

### 3.1.4.4 FreeBSD Driver

- Setting E830 and XXVDA2 OCP to only advertise 10G triggers AHS messages about failed link attempts before link comes up.
- ucmatose fails with RDMA\_CM\_EVENT\_UNREACHABLE (-60) on XXVDA2 OCP when running with -c 15000 connections.

### 3.1.4.5 ESX Driver

- <VMWARE> When instantiating the maximum number of VFs in NSX-T, adding a Transport Node afterwards might fail due to timeout.

### 3.1.4.6 Windows Driver

- TX counters are missing on Dell switches when PFC is enabled. Retrace counters are observed on hosts during testing, even with different PFC bandwidth allocations (50/50 split)

## 3.2 Intel® Ethernet 700 Series Network Adapters

### 3.2.1 General

- None for this release.

### 3.2.2 Intel® Ethernet Controller V710-AT2/X710-AT2/TM4

- Upon unloading the i40e driver when some VFs are assigned to VM before it fully operates may cause the VF to hang. To avoid the VF from hanging, destroy the VFs before unloading i40e Linux driver.

### 3.2.3 Linux Driver

- IRDMA SLES RPM installation with `rpm -ivh` may see a conflict with a directory due to multi-kernel installed.

**Workaround:** Use `--force` option to force install the rpm.

- In some cases `./nvmupdate64e` can't initialize the XL710 card in recovery mode.

```
Intel® Ethernet NVM Update Tool
NVMUpdate version 1.41.3.1
Copyright © 2013 - 2024 Intel Corporation.
```

```
Config file read.
```

```
Warning: Cannot initialize port: [00:059:00:00] Intel® Ethernet Converged Network
Adapter XL710-Q2
```

```
Warning: Cannot initialize port: [00:059:00:01] Intel® Ethernet Controller XL710
Generic ID
```

- Changing the inner or outer VLAN tag protocols after setting the private flag "`vf-true-promisc-support`" disables the promiscuity on the VF's VLAN interfaces.

### 3.2.4 Pre-Boot

- None for this release.

### 3.2.5 ESX Driver

- None for this release.

### 3.2.6 Firmware/NVM/NVM Update

- `AutoSpeedNegotiationEnabled` property returns current status of the Autonegotiation from the link, not the configured value to control AN.
- Selected customers reported physical link issue after NVM update. First failing release is 8.4, last working version 8.3. The error is occurring when called : `ifconfig up; ethtool -m`.
- After updating to NVM 4.11 in some servers, one port of X557/X527 OCP adapter appears link down from Windows Device Manager after reboot. (disabling SR-IOV increases repro rate)

**Workaround:** Link status is restored back to normal after unplug/plug cable or disable/enable the affected port from Windows Device Manager.

- NVM content might be corrupted after `nvmupdate` due to old FW version generating errors. In this cases "**i40e: eeprom check failed (-5), Tx/Rx traffic disabled**" will appear.

### 3.2.7 Windows Driver

- X710 has changed the value of DMAR "`DmaRemapping in Windows 11 (value == 1)`" due to BSOD.

### 3.2.8 ESX Driver

- When MTU is set to 9000, sending ICMP packets larger than 1500 bytes between ESXi hosts may occasionally trigger Receive Oversize Errors on the receiving side; this issue is rare and was observed only in one setup.

## 3.3 Intel® Ethernet 600 Series Network Adapters

### 3.3.1 General

- It may be possible that invalid PCIe configuration can cause that EEUpdate will not show the adapter in OS.

### 3.3.2 Linux Driver

- SLES 15SP6 - NIC ports may not be initialized via NVM Update Tool (via inventory switch). Devlink can be used instead - which is accessible by nvmupdate - if devlink flag.

### 3.3.3 Windows Driver

- After a reset event (e.g., CORER, GLOBR), the Windows Event Log should display a descriptive message, but currently it only shows the Event ID without the proper description.
- If two vNICs are connected through a vSwitch and the adapter is unexpectedly removed, the network connection may be lost. Restoring connectivity might require reinstalling the driver or rebooting the system. ,
- Speed and duplex values set on PF may not be properly displayed on VF. It's related only to 100MB and 1G speed.

### 3.3.4 VMware Driver

### 3.3.5 Firmware/NVM/NVM Update

- E610 incorrectly reports RDE property EthernetInterface.MaxFrameSize as 9022 bytes instead of 9728.
- After NVM Update from Firmware Recovery mode, additional NVM Update is required for adapter to get back into operational state.
- Unexpected sensor (ID 0x5) can be encountered on PLDM sensor list.
- Activity LED may not work properly on E610 XAT (single port device).
- Once NVM is updated via NVM Update Tool, it might be possible that target image is not loaded yet. If such situation occurs then warm reset (reboot) is required, then target image will be fully loaded.

### 3.3.6 ESX Driver

- None for this release.

## 3.4 Intel® Ethernet 500 Series Network Adapters

- For X550 Windows Driver design, vectors 0 through 7 are enabled at driver init and all RSS queues and queues from various TCs are mapped to it. But more vectors are available to use (GetVectorsAvailableForRssQueues = 16 , NumRssQueues = 8). After getting an RSS indirection table update, a new vector outside of 0 to 7 range can be chosen for a queue while doing the queue to CPU remapping process. If that vector is outside of the 0-7 range, current design will have trouble for the queue to CPU remapping process and cause 10400 event.

**Workaround:** Change RSS processor count & queue count max/default value to 8 to align with max 8 queue mapping support on driver to avoid issue.

- Intermittent Traffic Delivery Failure on SLES 15 SP5/SP6 with VF Connected to SW Bridge: an issue has been identified in SLES 15 SP5/SP6 where network traffic from a Virtual Function (VF) connected to a software bridge (SW bridge) may intermittently fail to reach the intended client. This problem is impacting the reliability of network communications in virtualized environments utilizing software bridges.

Result: traffic from vf connected to SW bridge sometimes may not reach a client.

### **3.5 Intel® Ethernet I350 Series Network Adapters**

- None for this release.

### **3.6 Legacy Devices**

- None for this release.

## 4.0 NVM Upgrade/Downgrade 800 Series/700 Series/600 series and X550

Refer to the Feature Support Matrix (FSM) links listed in [Feature Support Matrix](#) for more detail. FSMs list the exact feature support provided by the NVM and software device drivers for a given release.

## 5.0 Languages Supported

**Note:** This only applies to Microsoft Windows and Windows Server Operating Systems.

This release supports the following languages:

Languages	
English French German Italian Japanese	Spanish Simplified Chinese Traditional Chinese Korean Portuguese

## 6.0 Related Documents

Contact your Intel representative for technical support about Intel® Ethernet Series devices/adapters.

### 6.1 Feature Support Matrix

These documents contain additional details of features supported, operating system support, cable/modules, and so on.

Device Series	Support Link
Intel® Ethernet 800 Series: – E810 – E820 – E830 Intel® Ethernet Controller E810 and Intel® Ethernet Connection E82X Feature Comparison Matrix	<a href="https://cdrdv2.intel.com/v1/dl/getContent/630155">https://cdrdv2.intel.com/v1/dl/getContent/630155</a> <a href="https://cdrdv2.intel.com/v1/dl/getContent/739764">https://cdrdv2.intel.com/v1/dl/getContent/739764</a> <a href="https://cdrdv2.intel.com/v1/dl/getContent/861044">https://cdrdv2.intel.com/v1/dl/getContent/861044</a> <a href="https://cdrdv2.intel.com/v1/dl/getContent/751546">https://cdrdv2.intel.com/v1/dl/getContent/751546</a>
Intel® Ethernet 700 Series: – X710/XXV710/XL710 – X722 – X710-TM4/AT2 and V710-AT2	<a href="https://cdrdv2.intel.com/v1/dl/getContent/332191">https://cdrdv2.intel.com/v1/dl/getContent/332191</a> <a href="https://cdrdv2.intel.com/v1/dl/getContent/336882">https://cdrdv2.intel.com/v1/dl/getContent/336882</a> <a href="https://cdrdv2.intel.com/v1/dl/getContent/619407">https://cdrdv2.intel.com/v1/dl/getContent/619407</a>
Intel® Ethernet 600 Series: – E610	<a href="https://cdrdv2.intel.com/v1/dl/getContent/743366">https://cdrdv2.intel.com/v1/dl/getContent/743366</a>
Intel® Ethernet 500 Series	<a href="https://cdrdv2.intel.com/v1/dl/getContent/335253">https://cdrdv2.intel.com/v1/dl/getContent/335253</a>

## 6.2 Specification Updates

These documents provide the latest information on hardware errata as well as device marking information, SKU information, etc.

Device Series	Support Link
Intel® Ethernet 800 Series	<a href="https://cdrdv2.intel.com/v1/dl/getContent/616943">https://cdrdv2.intel.com/v1/dl/getContent/616943</a>
Intel® Ethernet 700 Series: – X710/XXV710/XL710 – X710-TM4/AT2 and V710-AT2	<a href="https://cdrdv2.intel.com/v1/dl/getContent/331430">https://cdrdv2.intel.com/v1/dl/getContent/331430</a> <a href="https://cdrdv2.intel.com/v1/dl/getContent/615119">https://cdrdv2.intel.com/v1/dl/getContent/615119</a>
Intel® Ethernet 600 Series: – E610	<a href="https://cdrdv2.intel.com/v1/dl/getContent/743364">https://cdrdv2.intel.com/v1/dl/getContent/743364</a>
Intel® Ethernet 500 Series – X550 – X540	<a href="https://cdrdv2.intel.com/v1/dl/getContent/333717">https://cdrdv2.intel.com/v1/dl/getContent/333717</a> <a href="https://cdrdv2.intel.com/v1/dl/getContent/334566">https://cdrdv2.intel.com/v1/dl/getContent/334566</a>
Intel® Ethernet 300 Series	<a href="https://cdrdv2.intel.com/v1/dl/getContent/333066">https://cdrdv2.intel.com/v1/dl/getContent/333066</a>
Intel® Ethernet 200 Series – I210 – I211	<a href="https://cdrdv2.intel.com/v1/dl/getContent/332763">https://cdrdv2.intel.com/v1/dl/getContent/332763</a> <a href="https://cdrdv2.intel.com/v1/dl/getContent/333015">https://cdrdv2.intel.com/v1/dl/getContent/333015</a>

## 6.3 Software Download Package

The release software download package can be found [here](#).

## 6.4 GitHub Ethernet Drivers and Utilities

For additional information regarding Linux kernel drivers, refer to the [GitHub](#) driver repositories.

## 6.5 Intel Product Security Center Advisories

Intel product security center advisories can be found at:

<https://www.intel.com/content/www/us/en/security-center/default.html>

## LEGAL

---

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

This document (and any related software) is Intel copyrighted material, and your use is governed by the express license under which it is provided to you. Unless the license provides otherwise, you may not use, modify, copy, publish, distribute, disclose or transmit this document (and related materials) without Intel's prior written permission. This document (and related materials) is provided as is, with no express or implied warranties, other than those that are expressly stated in the license.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors which may cause deviations from published specifications.

Copies of documents that are referenced in this document can be obtained by visiting the [Intel Resource and Documentation Center](#).

© Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.