



Release Notes: DL2 1.1.0.2 Leyard LED Control Software

July 19, 2018

Product Impacted: DL2/TWS cabinets

Software Part Number: 010-1599-01 Rev B, also known as version 1.1.0.2

Installation File Name: Leyard LED Control 1.1.0.2.exe

Engineering Change Order: 1009521

Reason for Change

- Has various minor updates

Firmware Compatibility Table

| Product | Firmware versions (MCU-MB FPGA-Module FPGA) | Notes |
|-------------|--|-----------------------------|
| DL2/TWS 0.9 | | |
| DL2/TWS 1.2 | 9553 12-6-27 | See Functional Issues below |
| DL2/TWS 1.5 | | |
| DL2/TWS 1.8 | | |

Refer to the most recent FW/SW Summary table for the latest FW/SW compatibility status as status may have changed after software was released

Functional Issues

- Full compatibility with 9552 generation cabinets was not verified though no issues were seen when using basic functions to control 9552 cabinets
- When a Read Parameters function is executed from the Advanced Controls tab, the Brightness and Brightness Limit parameters are not given. Use the Read Parameters function under the Basic Controls tab instead.
- Color Region, Refresh Rate, Read All Modules calibration data, and the Display Power commands are not properly working on the TWS 1.2—could be firmware or software issues. Do not use these functions.

end