

Software Release

Version 10.9 for

Microsoft Windows

Author:	3Dconnexion
Participant:	
Cc:	
Classification:	<i>Public documentation</i>

Document history summary:

Version	Author	Date	Status	Comment
7.0	3Dconnexion	2025-Jun-24	Final	Version 10.9.6 update
8.0	3Dconnexion	2025-Aug-12	Final	Version 10.9.7 update
9.0	3Dconnexion	2025-Oct-2	Final	Version 10.9.8 update
9.1	3Dconnexion	2025-Oct-10	Final	Documentation update only
10.0	3Dconnexion	2025-Dec-4	Final	Version 10.9.9 update
11.0	3Dconnexion	2026-Jan-16	Final	Version 10.9.10 update
12.0	3Dconnexion	2026-Mar-5	Final	Version 10.9.11 update
13.0	3Dconnexion	2026-Mar-9	Final	Version 10.9.12 update
14.0	3Dconnexion	2026-Apr-28	Final	Version 10.9.13 update
15.0	3Dconnexion	2026-Jul-3	Final	Version 10.9.14 update
16.0	3Dconnexion	2026-Sep-25	Final	Version 10.9.15 update

Contents

1.	INTRODUCTION	2
1.1	PURPOSE.....	2
1.2	TARGET AUDIENCE.....	2
1.3	RELEASE VERSION	2
1.4	DOCUMENT HISTORY	2
1.5	REFERENCES	3
2.	RELEASE HIGHLIGHTS	4
2.1	RELEASE OF SEPTEMBER 25, 2026.....	4
2.2	RELEASE OF JULY 3, 2026.....	4
2.3	RELEASE OF APRIL 28, 2026	4
2.4	RELEASE OF MARCH 9, 2026.....	4
2.5	RELEASE OF MARCH 5, 2026.....	4
2.6	RELEASE OF JANUARY 16, 2026	4
2.7	RELEASE OF DECEMBER 4, 2025	4
2.8	RELEASE OF OCTOBER 2, 2025	4
2.9	RELEASE OF AUGUST 12, 2025	5
2.10	RELEASE OF JUNE 24, 2025	5
2.11	RELEASE OF MAY 15, 2025	5
2.12	RELEASE OF APRIL 3, 2025	5
2.13	RELEASE OF JANUARY 9, 2025	5
2.14	RELEASE OF DECEMBER 9, 2024	5
2.15	RELEASE OF SEPTEMBER 27, 2024.....	5
2.16	RELEASE OF JULY 26, 2024.....	6
3.	WINDOWS SOFTWARE.....	7
3.1	DESCRIPTION.....	7
3.2	SUPPORTED OPERATING SYSTEMS	7
3.3	SUPPORTED 3Dconnexion PRODUCTS	7
3.4	PRODUCTS IN EXTENDED SUPPORT PERIOD	7
3.5	CHANGES TO 3DxWARE 10 FOR MICROSOFT WINDOWS	7

1. Introduction

1.1 Purpose

This document summarizes the changes in 3Dconnexion Software version as specified in section 1.3 below.

1.2 Target Audience

The target audience of this document is the general public using 3Dconnexion products, such as the SpaceMouse, CadMouse and Keyboard Pro.

1.3 Release Version

Release version 10.9.

1.4 Document History

Version 16.0

- Includes information on version 10.9.15 of 3DxWare 10 for Windows.

Version 15.0

- Includes information on version 10.9.14 of 3DxWare 10 for Windows.

Version 14.0

- Includes information on version 10.9.13 of 3DxWare 10 for Windows.
- Corrected change log for version 10.9.12: issue WIN-2163 applies only to SpaceMouse devices wireless connected to a Universal Receiver. Connections to a Keyboard Pro were unaffected.

Version 13.0

- Includes information on version 10.9.12 of 3DxWare 10 for Windows.

Version 12.0

- Includes information on version 10.9.11 of 3DxWare 10 for Windows.

Version 11.0

- Includes information on version 10.9.10 of 3DxWare 10 for Windows.

Version 10.0

- Includes information on version 10.9.9 of 3DxWare 10 for Windows.

Version 9.1

- Adds information on the support for version 2026 of Trimble SketchUp for Desktop in version 10.9.8 of 3DxWare 10 for Windows. The 3DxWare 10 software is unchanged.

Version 9.0

- Includes information on version 10.9.8 of 3DxWare 10 for Windows.

Version 8.0

- Includes information on version 10.9.7 of 3DxWare 10 for Windows.

Version 7.0

- Includes information on version 10.9.6 of 3DxWare 10 for Windows.

Version 6.0

- Includes information on version 10.9.5 of 3DxWare 10 for Windows.

Version 5.0

- Includes information on version 10.9.4 of 3DxWare 10 for Windows.
- Updated AutoCAD 2026 support information introduced in v. 10.9.2 of 3DxWare 10.

Version 4.0

- Includes information on version 10.9.3 of 3DxWare 10 for Windows.

Version 3.0

- Includes information on version 10.9.2 of 3DxWare 10 for Windows.

Version 2.0

- Includes information on version 10.9.1 of 3DxWare 10 for Windows.

Version 1.0

- Includes information on version 10.9.0 of 3DxWare 10 for Windows, published on July 26, 2024.

1.5 References

None.

2. Release Highlights

The following is a list of the most important changes and updates in this release.

2.1 Release of September 25, 2026

- Update 3DxWare 10 to version 10.9.15.
- New: 3Dconnexion Viewer new features “measurement tools”, “comments with saved views”, “markup annotations with rich text and graphical shapes”.
- New: Support PTC Creo Parametric version 2027.0.
- New: Multiple new driver configurations including for hypsoCAD and Procore.
- Change: Stability improvements and feature enhancements to driver software and the plug-ins for Dassault Systèmes SOLIDWORKS, Maxon Cinema 4D and Trimble SketchUp for Desktop.

2.2 Release of July 3, 2026

- Update 3DxWare 10 to version 10.9.14.
- New: Support version 2606 Series of Siemens NX.
- Change: Stability improvements and feature enhancements to driver software and the plug-in for Autodesk Civil 3D.

2.3 Release of April 28, 2026

- Update 3DxWare 10 to version 10.9.13.
- New: Multiple new driver configurations including for Autodesk Fusion Electronics, Mastercam and Revizto.
- Note: Additional stability improvements and feature enhancements to driver software and the plug-in software for Siemens NX.

2.4 Release of March 9, 2026

- Update 3DxWare 10 to version 10.9.12.
- Fix: SpaceMouse devices not recognized by driver when wirelessly connected to a Universal Receiver (issue [WIN-2163]).

2.5 Release of March 5, 2026

- Update 3DxWare 10 to version 10.9.11.
- New: Add new driver configurations for multiple applications, including Bentley MicroStation version 2026.
- Note: Additional stability improvements and feature enhancements to driver software and the plug-in software for Autodesk 3ds Max, AutoCAD and Maya.

2.6 Release of January 16, 2026

- Update 3DxWare 10 to version 10.9.10.
- New: Support version 2512 Series of Siemens NX.

2.7 Release of December 4, 2025

- Update 3DxWare 10 to version 10.9.9.
- Note: Stability improvements and feature enhancements to driver software and the plug-in software for Epic Games Unreal Editor, Maxon Cinema 4D and Siemens Solid Edge.

2.8 Release of October 2, 2025

- Update 3DxWare 10 to version 10.9.8.
- New: Support version 2026 of Maxon Cinema 4D.
- New: Support version 2026 of Trimble SketchUp for Desktop.
- Note: Additional stability improvements and feature enhancements to driver software and the plug-in software for Maxon Cinema 4D, PTC Creo Parametric, Siemens Solid Edge and Trimble SketchUp.

2.9 Release of August 12, 2025

- Update 3DxWare 10 to version 10.9.7.
- New: Support Autodesk Navisworks and Revit version 2026.
- New: Add new driver configurations for Materialise Magics and SolidCAM Machine Simulation.
- New: New “pan zoom” preset speed driver commands.
- Note: Additional stability improvements and feature enhancements to driver software.

2.10 Release of June 24, 2025

- Update 3DxWare 10 to version 10.9.6.
- New: Support version 2506 Series of Siemens NX.
- New: Add new driver configurations for multiple applications, including Cadwork 3D, Leica Cyclone 3DR and Moment of Inspiration.
- Note: Additional stability improvements and feature enhancements to driver software and the plug-in software for Siemens Solid Edge.

2.11 Release of May 15, 2025

- Update 3DxWare 10 to version 10.9.5.
- New: Add new driver configurations for multiple applications, including 3Dflow 3DF Zephyr, IMSI Design TurboCAD and MEDIT Link.
- Note: Stability improvements and additional feature enhancements to driver software and the plug-in software for Adobe Photoshop, Autodesk Maya and Siemens NX.

2.12 Release of April 3, 2025

- Update 3DxWare 10 to version 10.9.4.
- New: Add new driver configurations for multiple applications, including ArcGIS Earth, Tech Soft 3D SpinFire and Ultimaker Cura.
- New: Support versions 2026 of Autodesk 3ds Max and Maya.
- Note: Stability improvements and additional feature enhancements to driver software and the plug-in software for Maxon Cinema 4D, Siemens Solid Edge and Unity 3D Editor.

2.13 Release of January 9, 2025

- Update 3DxWare 10 to version 10.9.3.
- New: Support version 2412 Series of Siemens NX.
- Note: Stability improvements and additional feature enhancements to driver software and the plug-in software for Trimble SketchUp Desktop.

2.14 Release of December 9, 2024

- Update 3DxWare 10 to version 10.9.2.
- New: 16 new driver configurations, including for “SketchUp for Web”.
- New: “Global settings” for all CadMouse models and NPP.
- New: Support for SOLIDWORKS 2025 Desktop and Connected.
- New: Navigation Library solution for Siemens Solid Edge.
- New: Add support for version 2026 of Autodesk AutoCAD.
- Note: Stability improvements and additional feature enhancements to driver software and plug-in software for Autodesk 3ds Max, AutoCAD and Maya and Trimble SketchUp Desktop.

2.15 Release of September 27, 2024

- Update 3DxWare 10 to version 10.9.1.
- New: Support version 2025 of Maxon Cinema 4D.
- New: Driver configurations for Maxon ZBrushCore, Esri ArcGIS Pro, Graebert ARES Commander and multiple 3Shape applications.
- Note: Stability improvements and additional feature enhancements to driver software and the plug-in software for Autodesk Maya, PTC Creo Parametric and Trimble SketchUp Desktop.

2.16 Release of July 26, 2024

- Update 3DxWare 10 to version 10.9.0.
- New: Global Mapping feature for Keyboard Pro devices.
- New: Center-of-Rotation visualization in Trimble SketchUp.
- Change: Blender driver configuration improvements.
- Note: Stability improvements and additional feature enhancements to driver software.

3. Windows Software

3.1 Description

The 3DxWare 10 product includes most of the 3Dconnexion Windows software available from 3Dconnexion.

3.2 Supported Operating Systems

Supported Windows operating systems on Intel architecture:

- Windows 10 64-bit edition (version 2004 and newer)
- Windows 11

Note: Windows for Arm not supported.

3.3 Supported 3Dconnexion Products

Supported 3Dconnexion products:

- CadMouse
- CadMouse Compact
- CadMouse Compact Wireless
- CadMouse Pro
- CadMouse Pro Wireless
- CadMouse Pro Wireless Left
- CadMouse Wireless
- Keyboard Pro
- Numpad Pro
- SpaceMouse Compact
- SpaceMouse Enterprise
- SpaceMouse Pro
- SpaceMouse Pro Wireless
- SpaceMouse Wireless
- Universal Receiver

3.4 Products in Extended Support Period

Products in the Extended Support period:

- SpaceNavigator
- SpaceNavigator for Notebooks
- SpacePilot Pro

3.5 Changes to 3DxWare 10 for Microsoft Windows

Below is a breakdown of the changes implemented in this 3DxWare 10 version. These changes are listed under the individual components that make up the 3DxWare 10 product suite. If an application is not listed here, it does not mean that the application does not include support for 3D mice, as many applications are supported natively by the software vendor. However, if an application supports 3D mice, you will still need to download and execute 3DxWare 10 to install the device driver (3DxWinCore).

3.5.1 Current Version

The current version of 3DxWare 10: **10.9.15**.

3.5.2 Table of Included Products

The following table lists all included products in 3DxWare 10 and respective version and release date information.

Product Name	Version	Build date
3DxWare 10 for Windows	10.9.14	2026 Jun 30
3DxAdobe3D	1.5.1	2022 Jan 12
3DxAnalytics	1.0.5	2025 Jul 11
3DxAutoCAD	5.10.1	2026 Jun 3
3DxCinema4D	1.3.3	2026 Aug 26
3DxInventor	2.5.0	2024 Jan 23
3DxLcdApplets (SPP only)	1.5.1	2018 Feb 15
3DxMaya	6.0.21	2026 Feb 5
3DxNavisworks	1.0.3	2025 Jul 7
3DxNLServer	1.5.0	2025 Oct 9
3DxNX	3.5.15	2026 Jun 29
3DxPhotoshop	2.14.0	2025 May 9
3DxProENGINEER	2.4.12	2026 Aug 3
3DxRevit	1.0.5	2025 Jul 3
3DxSketchUp	5.8.0	2025 Sep 12
3DxSolidEdge	4.0.4	2025 Oct 28
3DxSolidWorks	3.9.0	2026 Sep 16
3DxStudio	7.0.21	2026 Feb 4
3DxTrainer	3.2.7	2020 Jul 9
3DxUnity3D	1.0.2	2025 Mar 14
3DxUnreal	1.3.6	2025 Oct 21
3DxViewer10	1.2.0	2024 Jul 18
3DxWinCore	17.9.14	2026 Jun 20
DemoPrograms	0.9.9	2025 Mar 14
LADP	3.06.109	2010 Aug 3

In italic: changed or new product packages since previous major release.

3.5.3 Changes to 3DxWare 10 since v. 10.8.21

The following component products were added (new): None.

The following component products were removed: 3DxMSOffice.

The following component products were updated: 3DxAnalytics, 3DxAutoCAD, 3DxCinema4D, 3DxMaya, 3DxNavisworks, 3DxNLServer, 3DxNX, 3DxPhotoshop, 3DxProENGINEER, 3DxRevit, 3DxSketchUp, 3DxSolidEdge, 3DxSolidWorks, 3DxStudio, 3DxViewer10, 3DxUnity3D, 3DxUnreal, 3DxWinCore (driver) and DemoPrograms.

Version 10.9.15 (b753; September 25, 2026). Sixteenth public release of 10.9.

- Updated: 3DxCinema4D v. 1.3.3 (b91, bba191c7; Aug 26, 2026).
- Updated: 3DxProENGINEER v. 2.4.12 (b66, 15584f14; Aug 3, 2026).
- Updated: 3DxSolidWorks v. 3.9.0 (r22141; Sep 16, 2026).
- Updated: 3DxViewer10 v. 2.0.0 (b10, branch "rel-v2.0.0", b4dc744f; Sep 22, 2026).
- Updated: 3DxWinCore v. 17.9.15 (b121, branch "rel-v17.9.15", d128237f; Sep 24, 2026).
- New: Distance, Area, Angle, Radius measurement tools in 3Dconnexion Viewer.
- New: Create comments with saved views in 3Dconnexion Viewer.
- New: Add markup annotations with rich text and graphical shapes in 3Dconnexion Viewer.
- New: [WIN-2290] Add support for PTC Creo 2027.
- New: [WIN-2374] Add new configuration file "TrimbleBusinessCenter.xml" for Trimble Business Center.
- New: [WIN-2376] Add new configuration file "PhotoModeler.xml" for PhotoModeler (NL based).
- New: [WIN-2377] Add new configuration file "CloudCompare.xml" for CloudCompare.
- New: [WIN-2378] Add new configuration file "iCAD_SX.xml" for iCAD SX (Fujitsu / iCAD Corporation).
- New: [WIN-2381] Add new configuration file "hypsoCAD.xml" for hypsocad.
- New: [WIN-2382] Add new configuration file "flexsim.xml" for FlexSim.
- New: [WIN-2384] Add new configuration file "ROBOGUIDE.xml" for FANUC ROBOGUIDE.
- New: [WIN-2390] Add new configuration file "Procore.xml" for Procore.

Version 10.9.14 (b745; June 30, 2026). Fifteenth public release of 10.9.

- Updated: 3DxAutoCAD v. 5.10.1 (b116, 57e0222e; Jun 3, 2026).
- Updated: 3DxNX v. 3.5.15 (b207, a58644fa; Jun 29, 2026).
- Updated: 3DxWinCore v. 17.9.14 (b3006, a3d07325; Jun 20, 2026).
- New: [WIN-2245] Include command icons for Autodesk Civil 3D.
- New: [WIN-2249] Support for NX 2606 Series (RTM NX2606.1700).
- New: [WIN-2250] Add new configuration file "AutoCAD_Civil_3D.xml" for Autodesk Civil 3D.
- Fix: [WIN-2241] Button flyout is visible after device disconnect.
- Fix: Do not show "Radial Menu" panel on taskbar (see [WIN-2212]).

Version 10.9.13 (b740; April 23, 2026). Fourteenth public release of 10.9.

- Updated: 3DxNX v. 3.5.14 (b202, 86fa342a; Mar 9, 2026).
- Updated: 3DxWinCore v. 17.9.13 (b2949, 39758ad2; Apr 23, 2026).
- New: [WIN-2192] Add new configuration file "MastercamNL.xml" for CNC Software Mastercam (NL based).
- New: [WIN-2196] Add new configuration file "Fusion360_Electronics.xml" for Autodesk Fusion Electronics (NL based).
- New: [WIN-2198] Add new configuration file "Revizto.xml" for Revizto.
- New: [WIN-2200] Add new configuration file "ZEISS_INSPECT.xml" for ZEISS INSPECT.
- New: [WIN-2201] Add new configuration file "ZEISS_CALYPSO.xml" for ZEISS CALYPSO.
- New: Include installation of "Visual C++ v14 (2015-2022) x64 Redistributable" v. 14.50.35719.
- Change: [WIN-2195] Update configuration file "Onshape.xml"
- Change: [WIN-2197] Update configuration file "AdobeSubstance3DPainter.xml"
- Change: [WIN-2199] Update configuration file "Revit.xml"
- Fix: [WIN-1297] Partially truncated text in 3DxPair / SMPWBW (German).
- Fix: [WIN-2173] Pairing SMW/SMPW is blocked for KBP that have firmware version 2.01 or older.
- Fix: [WIN-2174] Wrong text alignment in German language on the firmware update panel.
- Fix: [WIN-1501] NX - the name of Realize Shape environment in SmartUI is incorrect.
- Fix: [WIN-2188] Several programs crash after driver launch 3DxVirtualLCD, 3dxpiemenus, 3DxSmartUi.

Version 10.9.12 (b735; March 6, 2026). Thirteenth public release of 10.9.

- Updated: 3DxWinCore v. 17.9.12 (b2913, 954e15b9; Mar 6, 2026).
- Fix: [WIN-2163] SpaceMouse devices paired to a UR are ignored.

Version 10.9.11 (b734; March 3, 2026). Twelfth public release of 10.9.

- Updated: 3DxAutoCAD v. 5.10.0 (b115, 7883b9e0; Feb 10, 2026).
- Updated: 3DxMaya v. 6.0.22 (b170, e9e3b142; Feb 5, 2026).
- Updated: 3DxStudio v. 7.0.21 (b134, 34397b3e; Feb 4, 2026).
- Updated: 3DxWinCore v. 17.9.11 (b2912, da2bf937; Mar 3, 2026).
- New: [WIN-2139] Add new configuration file "NavisworksNL.xml" for Autodesk Navisworks.
- New: [WIN-2140] Add new configuration file "MicroStationNL.xml" for Bentley MicroStation version 2026.
- New: [WIN-2142] Add new configuration file "VisiQt.xml" for VISI Qt.
- New: [WIN-2144] Add new configuration file "STRAKON_Cube.xml" for STRAKON Cube.
- New: [WIN-2149] Add new configuration file "OneCNC.xml" for OneCNC.
- Change: [WIN-2141] Update configuration file "BricsCAD.xml".
- Change: [WIN-2143] Update configuration file "Visi.xml".
- Change: [WIN-2145] Update configuration file "Excel.xml".
- Change: [WIN-2146] Update configuration file "Vectorworks2021.xml".
- Change: [WIN-2147] Update configuration file "AutoCADIt.xml".
- Change: [WIN-2148] Update configuration file "ALLPLAN.xml" and added "ALLPLAN2026.xml".
- Change: [WIN-2150] SolidWorks - update of default profile.
- Fix: [WIN-1913] Notification about FW upgrade every time user starts machine when mouse connected via BT.
- Fix: [WIN-2159] 3DxProfileServer crashes on Polish OS.

Version 10.9.10 (b725; December 17, 2025). Eleventh public release of 10.9.

- Updated: 3DxNX v. 3.5.13 (b197, c80fd7d; Dec 17, 2025).

- Updated: 3DxWinCore v. 17.9.10 (r21980; Dec 10, 2025).
- New: [WIN-2018] Support for Siemens PLM NX 2512 Series.

Version 10.9.9 (b721; November 28, 2025). Tenth public release of 10.9.

- Updated: 3DxCinema4D v. 1.3.2 (b89, 9580843; Nov 19, 2025).
- Updated: 3DxNLServer v. 1.5.0 (r21893; Oct 9, 2025).
- Updated: 3DxSolidEdge v. 4.0.4 (b33, a9d3c38; Oct 28, 2025).
- Updated: 3DxUnreal v. 1.3.6 (b162, b7b29bc; Oct 21, 2025).
- Updated: 3DxWinCore v. 17.9.9 (r21964; Nov 28, 2025).
- Change: [SDK-66] Implement WAMP v2 in the Navigation Library Server.
- Fix: [WIN-2089] Navigation is incorrect after adding Camera from Deformer view in Maxon Cinema 4D.
- Fix: [WIN-2107] Pivot point is incorrectly focusing after adding the Deformer Camera view in Maxon Cinema 4D.
- Fix: [WIN-2012] CoR is changing its location from selected object during navigation despite use selected item is checked in Epic Games Unreal Editor.
- Fix: [WIN-2110] Keystrokes executed from Radial Menus can go on forever.
- Fix: [WIN-2111] Quick zoom doesn't zoom to cursor in perspective view in Siemens Solid Edge.
- Fix: [WIN-2112] Quick zoom doesn't zoom to cursor in perspective view in Maxon Cinema 4D.
- Fix: [WIN-1994] Wrong profile is loaded for Play in Editor mode and Blueprint class viewer in Epic Games Unreal Editor.
- Fix: [WIN-1995] Commands from UE in Asset and Play-in editor mode do not work in Epic Games Unreal Editor.
- Fix: [WIN-1627] Fly Mode and Drone Mode fail in 2D views in Epic Games Unreal Editor.
- Note: Epic Games Unreal Editor support limited to UE versions 4.23 to 5.3. Support for UE versions 5.4 to 5.7 is available from Fab.com.

Version 10.9.8 (b715; September 29, 2025). Nineth public release of 10.9.

- Updated: 3DxCinema4D v. 1.3.0 (b80, 6efecd2; Sep 29, 2025).
- Updated: 3DxProENGINEER v. 2.4.11 (r21849, branches/v2.4; Aug 14, 2025).
- Updated: 3DxSketchUp v. 5.8.0 (b190, c5de200; Sep 12, 2025).
- Updated: 3DxSolidEdge v. 4.0.3 (b31, a21a530; Sep 29, 2025).
- Updated: 3DxWinCore v. 17.9.8 (r21878; Sep 29, 2025).
- Removed: 3DxMSOffice (see [WIN-2104]).
- New: [WIN-2063] Support version 2026 of Maxon Cinema 4D for Microsoft Windows.
- New: [WIN-2087] Add support for version 2026 of Trimble SketchUp for Desktop.
- New: [WIN-2092] Add new configuration file "Ansys_Discovery.xml" for Ansys Discovery. Ansys Discovery - new default profile (moved [PMSW-849]).
- New: [WIN-2093] Add new configuration file "SpaceClaim.xml" for Ansys SpaceClaim. SpaceClaim - new default profile (moved [PMSW-851]).
- New: [WIN-2094] Add new configuration file "Ansys_ICEM_CFD.xml" for Ansys ICEM CFD. ICEM CFD - new default profile (moved [PMSW-872]).
- New: [WIN-2095] Add new configuration file "Ansys_CFD_Viewer.xml" for Ansys CFD Viewer. CFX-Pre - new default profile (moved [PMSW-873]).
- New: [WIN-2096] Add new configuration file "fe.screen-sim_Client_Simulation.xml" for fe.screen-sim Client. fe.screen-sim Client - new default profile (moved [PMSW-864]). See note below.
- New: [WIN-2100] Add new configuration file "Altair_EDEM.xml" for Altair EDEM. EDEM - new default profile (moved [PMSW-878]).
- New: [WIN-2105] Add new configuration file "CrealtyPrint.xml" for Creality Print. Creality Print - new default profile (moved [PMSW-878]).
- Change: [WIN-1867] Remove support for version 2.0 and all 32-bit editions of PTC Creo Parametric.
- Change: [WIN-2103] Update driver configurations for Microsoft Office after 3DxMSOffice plug-in removal.
- Fix: [WIN-1579] Position of the object isn't updated right away when moving it in Multiview in Maxon Cinema 4D.
- Fix: [WIN-2025] Fixed issue causing objects to disappear when clicking the Edit button while moving the SpaceMouse in Siemens Solid Edge.
- Fix: [WIN-2091] CoR isn't visible after plugin enabling in the first opened project in Siemens Solid Edge.

Version 10.9.7 (b709; August 6, 2025). Eighth public release of 10.9.

- Updated: 3DxAnalytics v. 1.0.5 (r21783; Jul 11, 2025).
- Updated: 3DxNavisworks v. 1.0.3 (b24, 034de2b; Jul 7, 2025).
- Updated: 3DxRevit v. 1.0.5 (b47, 919d51e; Jul 3, 2025).
- Updated: 3DxWinCore v. 17.9.7 (r21845; Aug 6, 2025).
- New: [WIN-2008] Speed presets for translation speeds.
- New: [WIN-2009] Add action interface support to Autodesk Revit 2026.
- New: [WIN-2010] Add action interface support to Autodesk Navisworks 2026.
- New: [WIN-2022] Add pairing update support in 3DxDFU.
- New: [WIN-2067] Add new configuration file "Materialise_Magics.xml" for Materialise Magics.
- New: [WIN-2068] Add new configuration file "SolidCAM_MachineSimulation.xml" for SolidCAM Machine Simulation.
- Change: [WIN-2066] Update configuration file "Blender.xml".
- Change: [WIN-2069] Update configuration file "BIMcollabZOOM.xml".
- Fix: [WIN-2011] Radial Menu keeps showing when executing a Macro with a long Pause.
- Fix: [WIN-2014] 3DxVirtualLCD.log constantly grows when no 3Dconnexion device is connected to the PC.

Version 10.9.6 (b699; Jun 23, 2025). Seventh public release of 10.9.

- Updated: 3DxNX v. 3.5.12 (r21742; Jun 23, 2025).
- Updated: 3DxSolidEdge v. 4.0.2 (b22, d50bbe8; May 21, 2025).
- Updated: 3DxWinCore v. 17.9.6 (r21741; Jun 13, 2025).
- New: [WIN-1845] Add support for Siemens PLM NX 2506.1700.
- New: [WIN-1988] Add new configuration file "Cadwork_3D.xml" for Cadwork 3D. cadwork 3D - new default profile (moved [PMSW-822]).
- New: [WIN-1989] Add new configuration file "Cyclone_3DR.xml" for Leica Cyclone 3DR. Leica Cyclone - new default profile (moved [PMSW-826]).
- New: [WIN-1996] Add new configuration file "EXModel.xml" for SHINING 3D EXModel. EXModel - new default profile (moved [PMSW-775]).
- New: [WIN-1997] Add new configuration file "QuickSurface.xml" for KVS QUICKSURFACE. QuickSurface - new default profile (moved [PMSW-778]).
- New: [WIN-1998] Add new configuration files "DesignSpark_Mechanical_Creator.xml", "DesignSpark_Mechanical_Engineer.xml" and "DesignSpark_Mechanical_Explorer.xml" for DesignSpark Mechanical. DesignSpark Mechanical - new default profiles (moved [PMSW-779]).
- New: [WIN-1999] Add new configuration file "Mol.xml" for Triple Squid's "Moment of Inspiration". Moment of Inspiration - new default profile (moved [PMSW-800]).
- Change: [WIN-2003] Update configuration file "ExoCADDental.xml". Exocad - new default profile update (moved [PMSW-832]).
- Fix: [WIN-1986] Wrong profile is being used by the driver for Solid Edge.

Version 10.9.5 (b693; May 13, 2025). Sixth public release of 10.9.

- Updated: 3DxMaya v. 6.0.21 (b161, 9302084; Apr 11, 2025).
- Updated: 3DxNX v. 3.5.11 (r21544; Mar 25, 2025).
- Updated: 3DxPhotoshop v. 2.14.0 (r21631; May 9, 2025).
- Updated: 3DxWinCore v. 17.9.5 (r21635; May 13, 2025).
- New: [WIN-1815] Add support for Photoshop desktop 2025 (v. 26).
- New: [WIN-1949] Add new configuration file "Capture.xml" for Capture from Capture Visualization AB. Capture - new default profile (moved [PMSW-805]).
- New: [WIN-1956] Add new configuration file "OrcaSlicer.xml" for OrcaSlicer. OrcaSlicer - new default profile (moved [PMSW-797]).
- New: [WIN-1957] Add new configuration file "AnycubicSlicerNext.xml" for Anycubic Slicer Next. AnycubicSlicerNext - new default profile (moved [PMSW-798]).
- New: [WIN-1958] Add new configuration file "GrabCAD_Print.xml" for GrabCAD Print. GrabCAD Print - new default profile (moved [PMSW-811]). See note below.
- New: [WIN-1959] Add new configuration file "PreForm.xml" for Formlabs PreForm. PreForm - new default profile (moved [PMSW-812]).
- New: [WIN-1960] Add new configuration file "LycheeSlicer.xml" for Mango 3D Lychee Slicer. LycheeSlicer - new default profile (moved [PMSW-813]).
- New: [WIN-1965] Add new configuration file "Medit_Link.xml" for MEDIT Link. Medit Link - new default profile (moved [PMSW-801]).

- New: [WIN-1967] Add new configuration file "TurboCAD.xml" for IMSI Design TurboCAD. TurboCAD - new default profile (Windows) (moved [PMSW-785]).
- New: [WIN-1968] Add new configuration file "ideaMaker.xml" for Raise 3D ideaMaker. ideaMaker - new default profile (moved [PMSW-814]).
- New: [WIN-1969] Add new configuration file "CHITUBOX_Pro.xml" for CHITUBOX Pro. Chitubox Pro - new default profile (moved [PMSW-820]).
- New: [WIN-1970] Add new configuration file "BambuStudio.xml" for Bambu Studio. Bambu Studio - new default profile (moved [PMSW-810]).
- New: [WIN-1971] Add new configuration file "3DF_Zephyr.xml" for 3Dflow 3DF Zephyr. 3DF Zephyr - new default profile (moved [PMSW-807]). See note below.
- New: [WIN-1973] Add new configuration file "CHITUBOX_Basic.xml" for CHITUBOX Basic. Chitubox Basic - new default profile (moved [PMSW-823]).
- New: [WIN-1976] Add new configuration file "3DSprint.xml" for 3D Systems 3D Sprint. 3D Sprint - new default profile (moved [PMSW-815]).
- New: [WIN-1977] Add new configuration file "AnycubicSlicer.xml" for ANYCUBIC AnycubicSlicer. AnycubicSlicer - new default profile (moved [PMSW-817]).
- New: [WIN-1979] Add new configuration file "Autodesk_Netfabb.xml" for Autodesk Fusion with Netfabb. Netfabb - new default profile (moved [PMSW-819]).
- New: [WIN-1980] Add new configuration file "Chaos_Vantage.xml" for Chaos Vantage. Chaos Vantage - new default profile (moved [PMSW-799]). See note below.
- New: [WIN-1981] Add new configuration file "Deswik_CAD.xml" for Deswik.CAD. Deswik - new default profile (moved [PMSW-802]).
- Change: [WIN-1866] Remove support for versions 8.0, 8.5 and all 32-bit editions of Siemens NX.
- Fix: [WIN-1201] Driver adjustments for the SpaceMouse have a delay.
- Fix: [WIN-1942] Polygons cannot be re-ordered when Autodesk Maya plugin is installed.
- Fix: [WIN-1944] CoR doesn't focus on child objects in Autodesk Maya.

Version 10.9.4 (b686; April 2, 2025). Fifth public release of 10.9.

- Updated: 3DxAnalytics v. 1.0.4 (r21521; Mar 18, 2025).
- Updated: 3DxCinema4D v. 1.2.2 (b70, a972860; Feb 27, 2025).
- Updated: 3DxMaya v. 6.0.20 (b157, ec5f051; Feb 26, 2025).
- Updated: 3DxNLServer v. 1.4.8 (r21486; Mar 7, 2025).
- Updated: 3DxSolidEdge v. 4.0.1 (b18, 7519200; Feb 21, 2025).
- Updated: 3DxStudio v. 7.0.19 (b127, 36065c3; Feb 26, 2025).
- Updated: 3DxUnity3D v. 1.0.2 (b32, 1ba8fa1; Mar 14, 2025).
- Updated: 3DxWinCore v. 17.9.4 (r21566; Apr 2, 2025).
- Updated: DemoPrograms v. 0.9.9 (Mar 14, 2025).
- New: [WIN-1582] Add support for Autodesk Maya version 2026.
- New: [WIN-1884] Add support for 3ds Max version 2026.
- New: [WIN-1871] Add new configuration file "UltiMaker_Cura.xml" for UltiMaker Cura.
- New: [WIN-1883] Add new configuration file SpinFire.xml for Tech Soft 3D SpinFire viewer.
- New: [WIN-1896] Add new configuration file "3Shape_ScanItDental.xml" for 3Shape ScanIt Dental.
- New: [WIN-1895] Add new configuration file "ArcGIS_Earth.xml" for ESRI ArcGIS Earth.
- New: [WIN-1896] Add new configuration file "3Shape_ScanItDental.xml" for 3Shape ScanIt Dental.
- New: [WIN-1899] Add new configuration file "Altair_SimSolid.xml" for Altair SimSolid.
- New: [WIN-1904] Add new configuration file "IRONCAD_COMPOSE.xml" for IRONCAD COMPOSE.
- New: [WIN-1905] Add new configuration file "IRONCAD_DRAFT.xml" for IRONCAD COMPOSE.
- New: [WIN-1906] Add new configuration file "IRONCAD_INOVATE.xml" for IRONCAD COMPOSE.
- New: [WIN-1907] Add new configuration file "Plasticity.xml" for NKallen Plasticity.
- New: [WIN-1908] Add new configuration file "3DCoat.xml" for Pilgway 3DCoat.
- New: [WIN-1910] Add new configuration file "3Shape_ShellDesigner.xml" for 3Shape ShellDesigner.
- New: [WIN-1911] Add new configuration file "Straumann_Nova.xml" (and icon) for Straumann Nova.
- New: [WIN-1917] Add new configuration file "Bluebeam_Revu.xml" for Bluebeam Revu.

- New: [WIN-1920] Add new configuration file "Straumann_coDiagnostiX.xml" for Straumann coDiagnostiX.
- New: [WIN-1921] Add new configuration file "TrueMap.xml" for TrueGage TrueMap.
- New: [WIN-1926] Add new configuration file "VMscope_CMPS.xml" for VMscope Cognition Master Professional Suite.
- New: [WIN-1927] Add new configuration file "SmartCAM_Pturn.xml" for SmartCAM Production Turning.
- Change: [WIN-1248] Enable moving camera/light sources in Unity 3D Editor.
- Change: [WIN-1849] Modify the installer check for minimum required system version.
- Change: [WIN-1870] Modify defaults of add-in settings "Draft: Keep Scale Constant", "Check for Collision" and "Sketch / Profile: Disable Rotation (2D)" in Siemens Solid Edge.
- Change: [WIN-1901] Update OpenSSL to v. 3.0.16 in the Navigation Library Proxy server (3DxNLServer).
- Change: [WIN-1932] Change wireless CadMouse firmware notification to update to v. 1.23.
- Fix: [WIN-1836] Restore defaults button appears for environment that does not change and does nothing there in PTC Onshape.
- Fix: [WIN-1851] 3DxNLServer crashes after refreshing web page.
- Fix: [WIN-1861] The navigation does not work after using mate options in Assembly environment in PTC Onshape.
- Fix: [WIN-1864] Auto CoR fails with some models in Maxon Cinema 4D.
- Fix: [WIN-1868] Changing navigation modes while using a camera with a target tag, may break the target in Maxon Cinema 4D.
- Fix: [WIN-1885] Builds crash when 3DxUnity3D is installed in the project (Unity 3D Editor).
- Fix: [WIN-1890] The object is jumping away while navigating in perspective view in PTC Onshape.

Version 10.9.3 (b671; December 20, 2024). Fourth public release of 10.9.

- Updated: 3DxNLServer v. 1.4.7 (r21316; Dec 20, 2024).
- Updated: 3DxNX v. 3.5.9 (r21306; Dec 17, 2024).
- Updated: 3DxSketchUp v. 5.7.1 (b184, c2777cb; Dec 17, 2024).
- Updated: 3DxWinCore v. 17.9.3 (r21309; Dec 19, 2024).
- New: [WIN-1729] Add support for Siemens PLM NX 2412.1700.
- Change: [WIN-1841] Update USGNX.xml. NX - improved new default profile.
- Fix: [WIN-1809] Closing connection to the NIServer causes deadlock.
- Fix: [WIN-1818] Closing connection to the NIServer causes crash.
- Fix: [WIN-1834] CoR isn't changed after using alt + MMB.

Version 10.9.2 (b665; December 6, 2024). Third public release of 10.9.

- Updated: 3DxAnalytics v. 1.0.3 (r21223; Nov 14, 2024).
- Updated: 3DxAutoCAD v. 5.9.0 (r21200; Nov 6, 2024).
- Updated: 3DxMaya v. 6.0.19 (b155, 30554c9; Dec 2, 2024).
- Updated: 3DxSketchUp v. 5.7.0 (b183, 1aedd8b; Nov 19, 2024).
- Updated: 3DxSolidEdge v. 4.0.0 (b17, fb23e0a; Nov 19, 2024).
- Updated: 3DxSolidWorks v. 3.7.0 (r21234; Nov 19, 2024).
- Updated: 3DxStudio v. 7.0.18 (b122, e5a7643; Dec 2, 2024).
- Updated: 3DxWinCore v. 17.9.2 (r21278; Dec 6, 2024).
- New: [WIN-1811] Add support for SOLIDWORKS version 2025
- New: [WIN-1341] Navigation Library solution for Siemens Solid Edge add-in.
- New: [WIN-1738] Add support for Autodesk AutoCAD 2026 (R25.1).
- New: [WIN-1749] Add new configuration file "D5_Render.xml" for D5 Render.
- New: [WIN-1750] Add new configuration file "ApplianceDesigner.xml" for 3Shape Appliance Designer.
- New: [WIN-1758] Add new configuration file "KeyShot.xml" for Luxion KeyShot.
- New: [WIN-1760] Add new configuration file "ALLPLAN.xml" for ALLPLAN.
- New: [WIN-1761] Add new configuration file "AC3D.xml" for Invis AC3D.
- New: [WIN-1762] Add new configuration file "3DViewStation.xml" for Kisters 3DViewStation.
- New: [WIN-1763] Add new configuration file "EarMouldDesigner.xml" for 3Shape EarMouldDesigner.
- New: [WIN-1765] Add new configuration file "OrthoAnalyzer.xml" for 3Shape OrthoAnalyzer.
- New: [WIN-1766] Add new configuration file "SEBuilder.xml" for Secret Ear Builder.
- New: [WIN-1767] Add new configuration file "SEDesigner.xml" for Secret Ear Designer.
- New: [WIN-1768] Add new configuration file "SEViewer.xml" for Secret Ear Viewer.

- New: [WIN-1785] Add new configuration file "ELAN_Pro_Panel.xml" for EPLAN Pro Panel.
- New: [WIN-1786] Add new configuration file "EPLAN_CStudio.xml" for EPLAN Cable proD Studio.
- New: [WIN-1787] Add new configuration files "EPLAN_HLibrary.xml" and "EPLAN_HStudio.xml" for EPLAN Harness proD Library and EPLAN Harness proD Studio.
- New: [WIN-1819] Add new configuration file "SketchUp_for_Web.xml" for Trimble SketchUp for Web.
- New: [WIN-1779] Application independent button bank UI for Numpad Pro.
- New: [WIN-1780] Application independent button bank UI for all CadMouse models.
- Change: Use "Object" as the default navigation mode and enable "Lock Horizon" in Autodesk Maya (see [WIN-1825]).
- Change: Use "Object" as the default navigation mode and enable "Lock Horizon" in Autodesk 3ds Max (see [WIN-1824]).
- Fix: [WIN-1783] Upper radial menu command has darker background after using it.
- Fix: [WIN-1810] 3DxService.dll doesn't load on PC with Serbian language.

Version 10.9.1 (b650; September 25, 2024). Second public release of 10.9.

- Updated: 3DxCinema4D v. 1.2.0 (b55, 47fd028; Sep 13, 2024).
- Updated: 3DxMaya v. 6.0.18 (b148, d48c4e9; Sep 16, 2024).
- Updated: 3DxProENGINEER v. 2.4.10 (r21054, branches/v2.4; Aug 9, 2024).
- Updated: 3DxSketchUp v. 5.6.1 (b179, dac63f9; Sep 11, 2024).
- Updated: 3DxWinCore v. 17.9.1 (r21132; Sep 25, 2024).
- New: [WIN-1735] Support version 2025 of Maxon Cinema 4D.
- New: [WIN-1718] Add new configuration for Gstarsoft GstarCAD.
- New: [WIN-1723] Add new configuration for Maxon ZBrushCore.
- New: [WIN-1724] Add new configuration for Esri ArcGIS Pro.
- New: [WIN-1725] Add new configuration for Graebert ARES Commander.
- New: [WIN-1745] Add new configuration for 3Shape ScanItLibrary.
- New: [WIN-1746] Add new configuration for 3Shape ModelBuilder.
- New: [WIN-1747] Add new configuration for 3Shape 3D Viewer.
- New: [WIN-1748] Add new configuration for 3Shape DentalDesigner.
- New: [WIN-1703] Add support for "Walk" navigation mode in Autodesk Maya.
- Change: [WIN-1702] Add "Drone" and "Walk" modes to Maya configuration.
- Change: [WIN-1482] Performance issue in big scenes in Autodesk Maya.
- Change: Update driver configurations for Alibre Design, Chief Architect, Enscape, Exocad, Google Earth Pro, HiCAD, KiCad, MicroStation, Navisworks, ProgeCAD and Twinmotion.
- Fix: [WIN-1522] Disappearing text on OSD.
- Fix: [WIN-1734] The CoR visibility option is not checked by default in Trimble Sketchup Desktop.

Version 10.9.0 (r3773; July 25, 2024). First public release of 10.9.

- Updated: 3DxSketchUp v. 5.6.0 (b176, 86b1058; Jul 16, 2024).
- Updated: 3DxViewer10 v. 1.2.0 (b32, 6e00913; Jul 18, 2024).
- Updated: 3DxWinCore v. 17.9.0 (r21038; Jul 25, 2024).
- New: [PMSW-4] Global Mapping for Keyboard Pro.
- New: [WIN-1184] Implemented the CoR icon display in the viewport. The feature is available only for SketchUp version 2023 and newer.
- Change: [WIN-1666] Improve driver configuration for Blender.
- Change: [WIN-1676] Allow "Modifier+PrtSc" shortcut to be entered as a Quick Macro.
- Change: Minimum supported version of SketchUp changed to 2021. Version 2020 and older no longer supported.
- Change: Upgrade Open Cascade Toolkit (OCCT) dependency to v. 7.8.0 in 3DxViewer10 (see note below).
- Fix: [WIN-1664] Driver feature to stop CadMouse "Smart Scroll" can affect applications.
- Fix: [WIN-1691] KBP Print Screen key in Global Settings does not run SnipAndSketch.
- Note: Support for JT file format not included in open-source release of OCCT.